

Bulletin

Date May 19, 1999

No ASQ-224-B
Page 1 of 1

Type Parts Manual Update
Policy Letter
√ Service Information

Attention Service Managers
√ Service and Parts Managers

Models LEA10, LEA30, and LEA60 Amana dryers

Issue Model number suffix misprinted

Action

- The following models were incorrectly produced with the number "2" suffix on the serial plate and bar codes.

Example: LEA10W2, PLEA10W2

<u>Model No.</u>	<u>Manufacturing No.</u>	<u>Serial No. Block</u>	<u>No. of Units</u>
LEA10AW2	PLEA10AW2	9902142918-9902143467	550
LEA30AW2	PLEA30AW2	9902172627-9902174126	1500
LEA60AW2	PLEA60AW2	9902176173-9902176772	600

- The above models are the same as the models without the suffix.
- Please make a note of this in your dryer service and parts information.