

# Bulletin



Comm. Microwave	Dehumidifier	Dishwasher
Dom. Microwave	Export Comm.	Heating Product
√ <b>Laundry Product</b>	PTAC Products	Range Product
Refrigerator/Fzr	Room Air Cond.	

**Date** July 31, 2000  
**No** ASQ-230-B  
Page 1 of 1

**Type** Parts Manual Update  
Policy Letter  
√ Service Information

**Attention** Service Managers  
√ Service and Parts Managers

**Models** ALE \ ALG565\*, ALE \ ALG665\*, and ALE \ ALG866\* Amana Dryers

**Issue** Three short beep signals at the beginning of Auto Cycle

**Warranty** Not covered by warranty / normal operation.

**Cause** Self-diagnostic test

**Action** Models ALE \ ALG565\*, ALE \ ALG665\*, and ALE \ ALG866\* Amana dryers may beep three short ½ second signals at the beginning of an Auto Cycle. This will happen if there are wet clothes lying across the moisture sensor bars at the beginning of the cycle.

This is a self-diagnostic test for the moisture sensor board and the beeping signal indicates the electronic circuit is functioning correctly. After this test is completed, the dryer will resume the Auto Cycle that was selected.

For more details on this self-diagnostic test, refer to the Service Manual, part number RS3200007.