

SERVICE POINTER

FOR IMMEDIATE ATTENTION OF YOUR SERVICE DEPARTMENT

LAUNDRY PRODUCTS REFRIGERATION PRODUCTS KITCHEN PRODUCTS

L8178722
February 2009

THIS SERVICE POINTER APPLIES TO THE FOLLOWING BRANDS:



KitchenAid

JENN-AIR

MAYTAG[®]

Amana


BY WHIRLPOOL CORPORATION

Admiral

 **Magic Chef**[®]

Whirlpool Sport and Maytag Epic Z Washers

Excessive Shaking and/or Vibration

Model Numbers:

WFW8200T	WFW8300S	WFW8400T	WFW8410S
WFW8500S	MHWZ400T	MHWZ600T	

Serial Numbers: Starting with HL

CUSTOMER CONCERN:

The customer may complain of excessive shaking and/or vibration.

CAUSE:

Several factors may contribute to the perception of excessive shaking or vibration.

CORRECTION:

Service kit, part number W10252502, is available to address all areas of concern. It will supply an instruction sheet that contains a check list and parts necessary to complete any of the repairs that may be needed. The use of all of the parts in the kit may not be necessary in each instance.