

# Bulletin

**Date** September 27, 1996

**No** ASQ-199-B  
Page 1 of 1

**Type** Parts Manual Update  
Policy Letter  
√ Service Information

**Attention** Service Managers  
√ Service and Parts Managers

**Models** Ultra-Mate® Washer and Dryer

**Issue** Reminder/Update on 437P3 and 438P3 Wire Harness Kit.

**Action** Improved wire harness kits, 437P3 and 438P3, were released to the field, October, 1986, for Ultra-Mate® washer/dryer on the models listed:

Wire Harness Kit	Models	Type
437P3	UE8031, HS8031 UG8091, HS8091 KS8031-4702	2-speed washer, electric dryer 2-speed washer, gas dryer Canadian unit only
438P3	UG8290 UE8230	1-speed washer, gas dryer 1-speed washer, electric dryer



## WARNING

- To reduce risk of electrical shock, fire, explosion, serious injury, or death:
- Disconnect electric power to washer/dryer before servicing.
- Never start washer/dryer with any guards/panels removed.
- Whenever ground wires are removed during servicing, wires must be reconnected to ensure washer is properly grounded.

Control panel harness, part 30172 (refer to Wire Harness Kit instructions, page 3, step A) is not available. If the control panel harness is required, order the parts below instead and follow step C, page 3 of the Wire Harness Kit instructions.

- Male terminal block Part 23037
- Terminals (order quantities as needed) Part 00116

Note: terminal extractor, 128P4, is needed for this procedure.