

Parts Bulletin

From Product Publications

Home Laundry Dryer Cylinder Roller Change

Date May, 1991

Bulletin Number PS91-7

Starting with serial number S6564538ZE, all home laundry dryers were manufactured with a new cylinder roller, Part No. 62649.

The new roller is equipped with a longer bearing, therefore, when replacing the old style roller with the new roller, the thrust washer, Part No. 23886, is not used, see illustration below. The thrust washer is used only with the old style roller, Part No. 56457. All other parts remain the same.

The parts department will supply only the new cylinder roller as the replacement part.

Suggested list price of the new cylinder roller is \$3.25. Price is F.O.B. Ripon, Wisconsin, and is subject to change without notice.

Please mark your records accordingly.



Product Publications
R.S.P.C.
P. O. Box 990
Ripon WI 54971

106

Amana [Residential Amana AEE953 Dryer Parts](#) Parts Diagram 08 - PARTS BULLETIN
Click on the part number to view part

Item	Original Part Number	Replaced By	Status	Part Description
1	23886		Not Available	WASHER, .578IDX1.25ODX1
2	56457	62649P		Roller- CY
3	Y62649	62649P		Roller- CY