


Amana FA9103 03 - 23907 & 24304 PUMP ASSEMBLIES



Amana [Residential Amana FA9103 Washer Parts](#) Parts Diagram 03 - 23907 & 24304 PUMP ASSEMBLIES
 Click on the part number to view part

Item	Original Part Number	Replaced By	Status	Part Description
1	23902		Not Available	ASSY,PULLEY
2	23960		Not Available	SCREW,1/4-20 X5/16 HEX
3	23897		Not Available	WASHER,.566IDX1.00ODX1
4	23882		Not Available	BEARING
5	26478			Wick
6	23901		Not Available	ASSY,PUMP BODY
7	23883		Not Available	BEARING
8	23885		Not Available	WASHER,8/16IDX1.00ODX.
9	23887		Not Available	WASHER,37/64IDX63/64OD
10	23900			Seal
11	23886		Not Available	WASHER,.578IDX1.25ODX1
12	23898			Assembly, Impeller
13	23892		Not Available	GASKET
14	23877		Not Available	BOTTOM,PUMP
"	23876		Not Available	PUMP COVER
15	20161			Screw, 5/16-18 X 1-1/16

16	23879		Clamp, Pump
17	20176		Washer, .2656 ID x 9/16 OD
18	03189		LoCkwasher, 1/4 Std-C P
19	20275	27001225	Nut, Jam Mid Lock 1/4-20
20	Y00000000	Not Available	SEE NOTE MOUNTING PLATE -- (SEE PAGE 19, KEY 29)
21	24390		Bolt
22	Y24304	Not Available	PUMP ASSEMBLY
"	23907	Not Available	ASSY,PUMP
NI	211P3		Kit, Pump Repair

