

MANUFACTURED UNDER ONE OR MORE OF THE FOLLOWING US PATENTS:


4669200, 4700495, 4754556, 4840285, 4865366, 4899464,  
4908959, 4989347, 5066050, 5560120, 5809828, 6020698,  
6047486, 6199300, 6446357, D314261, D314262, D457991,  
D457992

MANUFACTURED UNDER ONE OR MORE OF THE FOLLOWING CANADIAN PATENTS:  
FABRIQUE SOUS UN OU PLUSIEURS DES BREVETS CANADIENS SUIVANTS:

1273387, 1315539, 2016304

MANUFACTURADO BAJO UNA O MAS DE LAS SIGUIENTES PATENTES MEXICANAS:

189136



| PART NO   | REV |
|-----------|-----|
| W10185985 | H   |

**LEGEND**

- COMPONENT MAY OR MAY NOT BE USED
- TIMER CONSTRUCTION
- TERMINAL CONSTRUCTION
- SPLICE
- IN LINE CONNECTION

CAUTION: LABEL ALL WIRES PRIOR TO DISCONNECTION WHEN SERVICING CONTROLS. WIRING ERRORS CAN CAUSE IMPROPER AND DANGEROUS OPERATION. VERIFY PROPER OPERATION AFTER SERVICING.

**WARNING - DISCONNECT FROM ELECTRICAL SUPPLY BEFORE SERVICING UNIT.**

