

MANUFACTURED UNDER ONE OR MORE OF THE FOLLOWING US PATENTS:


4669200, 4700495, 4754556, 4840285, 4865366, 4899464,
4908959, 4989347, 5066050, 5560120, 5809828, 6020698,
6047486, 6199300, 6446357, D314261, D314262, D457991,
D457992

MANUFACTURED UNDER ONE OR MORE OF THE FOLLOWING CANADIAN PATENTS:
FABRIQUE SOUS UN OU PLUSIEURS DES BREVETS CANADIENS SUIVANTS:

1273387, 1315539, 2016304

MANUFACTURADO BAJO UNA O MAS DE LAS SIGUIENTES PATENTES MEXICANAS:

189136



PART NO	REV
W10185985	H

LEGEND

- COMPONENT MAY OR MAY NOT BE USED
- TIMER CONSTRUCTION
- TERMINAL CONSTRUCTION
- SPLICE
- IN LINE CONNECTION

CAUTION: LABEL ALL WIRES PRIOR TO DISCONNECTION WHEN SERVICING CONTROLS. WIRING ERRORS CAN CAUSE IMPROPER AND DANGEROUS OPERATION. VERIFY PROPER OPERATION AFTER SERVICING.

WARNING - DISCONNECT FROM ELECTRICAL SUPPLY BEFORE SERVICING UNIT.

