


MANUFACTURED UNDER ONE OR MORE OF THE FOLLOWING US PATENTS:  
 4669200, 4700495, 4754556, 4840285, 4865366, 4899464,  
 4908959, 4989347, 5066050, 5560120, 5809828, 6020698,  
 6047486, 6199300, 6446357, D314261, D314262, D457991,  
 D457992

MANUFACTURED UNDER ONE OR MORE OF THE FOLLOWING CANADIAN PATENTS:  
 FABRIQUE SOUS UN OU PLUSIEURS DES BREVETS CANADIENS SUIVANTS:

1273387, 1315539, 2016304

MANUFACTURADO BAJO UNA O MAS DE LAS SIGUIENTES PATENTES MEXICANAS:

189136



| PART NO   | REV |
|-----------|-----|
| WI0185993 | E   |

**LEGEND**

- — COMPONENT MAY OR MAY NOT BE USED
- — TIMER CONSTRUCTION
- TERMINAL CONSTRUCTION
- SPLICE
- ∞ IN LINE CONNECTION

CAUTION: LABEL ALL WIRES PRIOR TO DISCONNECTION WHEN SERVICING CONTROLS.  
 WIRING ERRORS CAN CAUSE IMPROPER AND DANGEROUS OPERATION.  
 VERIFY PROPER OPERATION AFTER SERVICING.

**WARNING** - DISCONNECT FROM ELECTRICAL SUPPLY BEFORE SERVICING UNIT.

