

Dexter WCAD20KCS-12SZ (T350) Labels And Diagrams

No Parts
Drawing



[Dexter Commercial Dexter WCAD20KCS-12SZ \(T350\) Washer Parts](#) Parts Diagram Labels And Diagrams

[Click on the part number to view part](#)

Item	Original Part Number	Replaced By	Status	Part Description
*	9506-239-001		Not Available	Wiring Diagram, Coin, Optical
"	9506-239-001		Not Available	Wiring Diagram, Coin, Optical
"	9506-245-001		Not Available	Wiring Diagram, Coin, Electronic Acceptor
"	9506-241-001		Not Available	Wiring Diagram (Easy Card)
"	9506-321-001		Not Available	Wiring Diagram, CN, No Acceptor
"	8507-273-001		Not Available	Instructions Spin Direction
"	9506-238-001		Not Available	Wiring Schematic, Coin, Optical
"	9506-238-001		Not Available	Wiring Schematic, Coin, Optical
"	9506-244-001		Not Available	Wiring Schematic, Coin, Electronic Acceptor
"	9506-240-001		Not Available	Wiring Schematic, Easy Card

"	9506-320-001	Not Available	Wiring Schematic, CN, No Acceptor
"	8507-330-001	Not Available	Instruction Transient Voltage Suppressor
"	8502-614-004		Label-Warning,High voltage
"	8502-619-004		Label Fusing & Installation
"	8511-001-002	Not Available	Label Quality
"	8514-169-001	Not Available	Booklet Owners

the laundry company®

the laundry company®

the laundry company®