


Amana LG9209L2 (BOM: PLG9209L2) 12 - HEATER BOX ASSY
REPLACEMENT



Amana Residential Amana LG9209L2 (BOM: PLG9209L2) Dryer Parts Parts Diagram 12 - HEATER BOX ASSY
REPLACEMENT

Click on the part number to view part

Item	Original Part Number	Replaced By	Status	Part Description
1	500179P	503605		Assembly, Heater Duct
2	500820			Outlet Cover
3	501668	503688		Screw, 10B-16 X .34 I

the laundry company®