


Hoover HDE2000KW 07 - WIRING INFORMATION



CONNECT DRYER TO 230 V.A.C., 60 HZ. 1 PHASE INDIVIDUAL BRANCH CIRCUIT PROTECTED BY MAXIMUM 30 A. FUSES. ALWAYS GIVE THE SERIAL & MODEL NUMBERS WHEN WRITING ABOUT THIS DRYER OR ORDERING PARTS

Hoover [Residential Hoover HDE2000KW Dryer Parts](#) Parts Diagram 07 - WIRING INFORMATION
 Click on the part number to view part

Item	Original Part Number	Replaced By	Status	Part Description
NI	15001219		Not Available	WIRING INFORMATION

